



Environmental and Analytical Services-Since 1994
California State Accredited Laboratory in Accordance with ELAP Certificate # 2332

Prepared for: DCOR, LLC
290 Maple Court Suite #290
Ventura, CA 93003
Attn: Jay Rao

Report Date: March 18, 2016
Laboratory Number: 160591
Project Name: PF Hillhouse Produced Water-Monthly
Sampled by: David Hart

Enclosed are the analysis results for samples received March 8, 2016 with the Chain of Custody document. The sample was received in good condition, at 7°C, and it was identified and assigned the laboratory ID number listed below:

SAMPLE DESCRIPTION

CAS LAB NUMBER ID

Produced Water

160591-01

By my signature below, I certify that the results contained in this laboratory report comply with applicable standards for certification by the California Department of Public Health's Environmental Laboratories Accreditation Program (ELAP), both technically and for completeness, and that, based on my inquiry of the person or persons directly responsible for performing the analyses, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete.

Lance Lewy-Laboratory Director

If you have any further questions or concerns, please contact me at your convenience. This report consists of 1 page excluding the cover letter and the Chain of Custody.

This report shall not be reproduced except in full without the written approval of CAS. The test results reported represent only the item being tested and may not represent the entire material from which the sample was taken.

CERTIFICATE OF ANALYSIS

Client: DCOR, LLC (Hillhouse)	Date Sampled: 03/07/16
CAS LAB NO: 160591	Date Received: 03/08/16
Analyst: AN	Date Analyzed: 03/14/16
	Sample Matrix: Water

SALINITY
EPA Method SM 210C

CAS Lab #	Sample ID	RESULTS (g/Kg)	Dilution Factor	PQL (g/Kg)
160591-01	Produced Water	20	1	1.0

QUALITY CONTROL REPORT

160591-MB	Method Blank	BQL	1	1.0
-----------	--------------	-----	---	-----

g/Kg: grams/Kilograms
PQL: Practical Quantitation Limit
BQL: Below Quantitation Limit

CAPCO ANALYTICAL

SERVICES

1536 Eastman Avenue
Ventura, CA 93003

(805) 644-1095 Fax 644-9947

CHAIN OF CUSTODY RECORD

REPORT:

Fax

(805) 535-2075

Company

DCOR, LLC.

Address

290 Maple Court, Suite 290
Ventura, CA, 93003

BILL TO:

P.O. #

DCOR, LLC.

Company:

Address

160591

PROJ. NO.

PROJECT NAME:

Hillhouse

Produced Water-Monthly

CONTAINER TYPES
A=Amber Bottle, G=Glass,
P=Plastic, V=Vial, O=Other
Matrix

Analysis

Salinity

3/15
3/16

Remarks

Produced Water Temp 74°

SAMPLER'S SIGNATURE: *David Hest*

Print Name: David Hest

Sample NO. 1 Date Sampled 3-7-16 Time Sampled 06:25

Grab X

Sample Description Produced Water

Water X

Soil

Sludge

Other

#

Container

Type

1

P

X

Relinquished by: (Signature) *[Signature]*

Date: 3-8-16

Received by: (Signature) *[Signature]*

Water

Soil

Sludge

Other

#

Container

Type

1

P

X

Relinquished by: (Signature) *[Signature]*

Date: 3-8-16

Received by: (Signature) *[Signature]*

Water

Soil

Sludge

Other

#

Container

Type

1

P

X

Relinquished by: (Signature) *[Signature]*

Date: 3-8-16

Received by: (Signature) *[Signature]*

Water

Soil

Sludge

Other

#

Container

Type

1

P

X

Relinquished by: (Signature) *[Signature]*

Date: 3-8-16

Received by: (Signature) *[Signature]*

Water

Soil

Sludge

Other

#

Container

Type

1

P

X